

WEIGHT CHART / METER

SIZE Rectangle (MM)	0.60	0.70	0.80	0.90	1.00	1.20	1.50	2.00	2.50	3.00	4.00
10x20	0.28	0.32	0.37	0.41	0.45	0.54					
10x30	0.37	0.43	0.49	0.55	0.61	0.73	0.90				
10x40		0.54	0.62	0.70	0.77	0.92	1.14				
10x50			0.75	0.84	0.93	1.11	1.38				
10x60				0.98	1.09	1.30	1.62				
10x70				1.13	1.25	1.49	1.85				
20x30	0.47	0.54	0.62	0.70	0.77	0.92	1.14	1.49			
20x40	0.56	0.66	0.75	0.84	0.93	1.11	1.38	1.81			
20x60		0.88	1.00	1.13	1.25	1.49	1.85	2.45			
20x80				1.41	1.57	1.87	2.33	3.08			
25x50	0.71	0.82	0.94	1.05	1.17	1.40	1.73	2.29			
25x75				1.41	1.57	1.87	2.33	3.08			
26x13	0.37	0.43	0.49	0.55	0.61	0.73	0.90	1.17			
30x50	0.76	0.88	1.00	1.13	1.25	1.49	1.85	2.45			
35x60				1.41	1.57	1.87	2.33	3.08			
40x60				1.41	1.57	1.87	2.33	3.08	3.82	4.55	5.97
40x80				1.70	1.89	2.26	2.81	3.72			
50x110				2.27	2.52	3.02	3.76	4.99	6.21	7.42	9.79

FORMULA - [Mother O. D. (mm) - Thickness (mm)] x Thickness (mm) x 0.02475 = Wt. in running meter
Mother O. D. - [(Length (mm) + Width (mm)) x 2 x 0.3175]