


TRIP CONTACTOR NEUTRAL

TRIP CONTACTOR PHASE

FOR CONTACTOR TRIPPING PLEASE USE NO AND COM (16 AND 17 NO.) POINT OF TRIPPING RELAY

FOR MOTOR TRIPPING PLEASE USE COM AND NC (17 AND 18 NO.) POINT OF TRIPPING RELAY



www.precisionzone.co.in			
Precision Zone Ludhiana			
Size A3	FCSM No.	DWG No. PZ_DR_DM_9990_303X	Rev
Scale Not to Scale	Sheet		